

42RLE

Precision International's continual update research has resulted in the need to add the following parts for the 42RLE

Kits affected:

PI# KP61900A, KP61900AX, K61900-5 and all related Master and Banner kits.

In order to increase coverage through 2011, we will add the following:

- 1 pc. 31562 O-Ring VLP* Solenoid No. 1
- 1 pc. 31827 O-Ring, VLP* Solenoid No. 2 (Sm)
- 1 pc. 77021 O-Ring, VLP* Solenoid No. 2 (Lg)
- 1 pc. 31575C Screen, VB Regulator
- 1 pc. 31587 Seal VLP* Motor Harness

*VLP=Variable Line Pressure

Parts will be found in kits after date code 12/1/93

7/10/12



THE PROBLEM SOLVERS